





MULLING A MONARCH™ DOUBLE HUNG REPLACEMENT WINDOW TO A MONARCH™ REPLACEMENT PICTURE WINDOW TO A MONARCH™ DOUBLE HUNG REPLACEMENT WINDOW UTILIZING SNAP MULLIONS

#8 A PAN HEAD STAINLESS
STEEL SCREWS
(NOT BY LOCKHEED)



REMOVE WAFER HEAD JAMB ADJUSTERS FROM EACH
MULLED JAMB AND PLACE SAME SCREW INTO FACTORY
PREPUNCHED HOLE

THERE SHOULD BE A TOTAL OF SIX SCREWS PER MULLION ASSEMBLY



NOT TO SCALE



WINDOW CORP.

Route 100, Pascoag, Rhode Island 02859
TEL: (401) 568-3061
FAX: (401) 568-2273
www.lockheedwindow.com

Form #685
Rev 1/09